

MAHARASHTRA POLLUTION CONTROL BOARD REGIONAL OFFICE-KALYAN

Tel. No. (0251) 2310167/2310212

Fax No. (0251) 2310192

Visit us on: <http://mpcb.gov.in>

E-mail: rokalyan@mpcb.gov.in



Siddhivinayak Sankul,
3rd Floor, Near Oak Baug,
Station Road,
Kalyan (West)-421 301.

No. MPCB/CD/ 2409250003
Email / Hand Delivery / RPAD

Date :- 25 / 09 / 2024

To,
M/s. Shree Pandurang Enterprises,
Gut No. 372(II), Village-Usar,
Tal-Wada, Dist-Palghar.

Sub :- Closure Directions u/s 33A of the Water (Prevention & Control of Pollution) Act, 1974 and u/s 31A of the Air (Prevention & Control of Pollution) Act, 1981.

- Ref :-**
- 1) Consent to Operate granted by the Board on 28/03/2023.
 - 2) Proposed Direction issued by the Board on 18/03/2024.
 - 3) Interim Directions issued by the Board on 04/04/2024.
 - 4) Legal action proposal No. MPCB-LEGAL_ACTIONS-281021029.
 - 5) Approval of competent authority of the MPC Board dtd. 23/07/2024.

WHEREAS, the Maharashtra Pollution Control Board has granted Consent to Operate u/s 26 of the Water (Prevention and Control of Pollution) Act, 1974 and u/s 21 of the Air (Prevention and Control of Pollution) Act, 1981 & Authorization under Rule 6 of the Hazardous and Other Wastes (Management and Trans-boundary Movement) Rules, 2016, on 21/09/2021 which was valid upto 31/08/2027 subject to certain terms and conditions.

AND WHEREAS, it was also obligatory on your part to provide adequate and efficient pollution control devices and take adequate measures to control air & water pollution, so as to achieve the consented standards.

AND WHEREAS, Maharashtra Pollution Control Board had issued Proposed Directions to the unit on 18/03/2024 and Interim Directions issued on 04/04/2024. **AND WHEREAS**, the Board is in receipt of complaint against the industry. **AND WHEREAS**, SRO Kalyan-3 have reported that

1. The Effluent Treatment Plant(ETP) not found in operation.
2. Industry has not provided closed shade for storage for waste tyre, carbon black and steel wire.
3. Industry has not provided water fogging system in the entire premises of industry.
4. Industry has not provided dyke wall for oil storage tank hence observed oil spillage and spread oil near oil storage tank.
5. Industry has not provided mechanized feeding system.
6. Smoke leakages were observed from the reactor.
7. Industry has not complied SOP s of CPCB.
8. During the visit, Air Pollution Control System (APC) was not in operation resulting in heavy emission in atmosphere.
9. Industry is not using mechanized unloading system for carbon black.
10. Carbon black spreading in the premises and surrounding area of industry was noticed.

11. The industry has not complied with all points of SOPs and Interim Directions.

AND WHEREAS, in spite of giving reasonable opportunity, after examining the record of your case and the reports of the officers of the Board, it has been observed that you have not complied with consent conditions and Interim Directions and causing Air pollution problems in the surrounding area knowingly and willfully.

NOW THEREFORE, in view of the above non-compliances, you are hereby directed to stop your manufacturing activities forthwith in a safe manner, failing which, the Board will have no option than to initiate appropriate legal action under the provisions of the Water (Prevention & Control of Pollution) Act, 1974 and the Air (Prevention & Control of Pollution) Act, 1981.

This is issued with the approval of competent authority of the MPC Board.

Dr. R. A. Rajput
Regional Officer, Kalyan

Copy submitted for information to:

The Member Secretary, M.P.C. Board, Mumbai.

Copy f.w.cs to:

- 1) Regional Officer (BMW), M.P.C. Board, Mumbai.
- 2) Law Officer, MPC Board, Mumbai.

Copy f.w.cs to:

- 1) Ex. Engineer / Addl. Engineer / Sub Divisional Engineer / Deputy Engineer, Maharashtra State Electricity Distribution Co. Ltd., Wada, Tal. Wada, Dist. Palghar – It is directed to disconnect electricity supply to the aforesaid unit & inform this office accordingly.
- 2) Grampanchayat, Usar, Wada, Tal. Wada, Dist. Palghar - It is directed to disconnect water supply to the aforesaid unit & inform this office accordingly.

Copy to: Sub Regional Officer, MPC Board, Kalyan-3– It is directed to take follow up and ensure the compliance of the aforesaid directions. It is also directed to ensure that these Directions to be served to the industry and competent authorities & submit the compliance verification report.