

MAHARASHTRA POLLUTION CONTROL BOARD REGIONAL OFFICE-KALYAN

Tel. No. (0251) 2310167/2310212
Fax No. (0251) 2310192
Visit us on: <http://mpcb.gov.in>
E.mail: rokalyan@mpcb.gov.in



Siddhivinayak Sankul,
3rd Floor, Near Oak Baug,
Station Road,
Kalyan (West) – 421 301.

No. : MPCB/CD/2005070004

Date:- 07/05/2020

To,
M/s.S.R.S. Poly Yarn
H.No.248, A-1, Opp. Super Sizing,
New Kaneri, Khoka Compound,
Tal.- Bhiwandi, Dist.-Thane

Sub: Closure Directions u/s 33A of the Water (P&CP) Act, 1974 & u/s 31 A of the Air (P&CP) Act, 1981 r. w. Hazardous & Other Wastes (M&TM) Rules, 2016.

- Ref:** 1) Consent granted by the Board to your industry.
2) Visit of Board officials to your unit on 07/03/2020.
3) Proposal submitted by Sub-Regional Office, Bhiwandi dtd. 16/03/2020.
4) Approval received from HQ dtd. 27/03/2020.
5) Enforcement Policy Published by the Board vide dtd. 29/02/2016.

WHEREAS, you are operating the industry in the pollution prevention area declared under the Provisions of the Water (P&CP) Act, 1974 and the Air (P&CP) Act, 1981 and the Hazardous & Other Wastes (Management & Transboundary Movement) Rules, 2016.

AND WHEREAS, it is obligatory on your part to obtain Conditional Combined Consent and Authorization to operate your industrial plant to discharge sewage and trade effluent in water pollution prevention area subject to certain terms and conditions more precisely under the provisions of 26 of the Water (P&CP) Act, 1974 and section 21 of the Air (P&CP) Act, 1981 and Hazardous & Other Wastes (Management & Transboundary Movement) Rules, 2016.

AND WHEREAS, it was also obligatory on your part to provide adequate and efficient pollution control devices and take adequate measures to control air & water pollution from all sources so as to achieve the standards prescribed in the Environment (Protection) Act 1986 and to disposed the Hazardous Waste to CHWTSDF.

AND WHEREAS, this office has received proposal from Sub-Regional Office, MPCB, Bhiwandi and reported following non- compliances.

- 1) JVS analysis result of ETP outlet exceeding the consented prescribed limits for parameter m pH 5 and COD 436 mg/lit .
- 2) You have not upgraded existing effluent treatment plant as per Interim Direction dtd. 10/01/2020.
- 3) JVS analysis result of Stack Monitoring dtd. 30/01/2019 exceeding the consented prescribed limits for parameters of TPM – 451 mg/m³ & Stack Monitoring dtd. 07/03/2020 exceeding the consented prescribed limits for parameters of SO₂ – 121.6 Kg/D.

...2

AND WHEREAS, after examining all the reports and records available with this office I have come to the conclusion that you are knowingly and willfully violating the provisions of the Water (P&CP) Act, 1974 and Air (P&CP) Act, 1981.

NOW THEREFORE, in exercise of powers conferred upon me by the Board u/s 33A of the Water (P&CP) Act, 1974 and u/s 31A of the Air (P&CP) Act, 1981. I, the Regional Officer, Kalyan hereby direct you to stop your manufacturing activity taking all precautionary measures for safe closure of the unit within 48 hours from receipt of this direction. It may also be noted that, the competent authorities are being directed to disconnect the electricity and water supply to your unit.

This is issued with approval from competent authority.



Regional Officer, Kalyan

Copy submitted for information to:

1. Member Secretary, M.P.C. Board, Mumbai.
2. Law Officer M.P.C. Board, Mumbai.
3. Principal Scientific Officer, M.P.C. Board, Mumbai.

Copy f.w.cs to:

- 1) The Executive Engineer, Torrent Power Ltd., Old Agra Road, AnjurPhata, Bhiwandi-421302 - He is directed to disconnect electricity supply to the aforesaid unit after completion of 24 hours for safe closure of the unit & inform this office accordingly.
- 2) The Executive Engineer (Water Supply), Bhiwandi Nizampur Municipal Corporation, Bhiwandi - He is directed to disconnect water supply to the aforesaid unit after completion of 24 hours for safe closure of the unit & inform this office accordingly

Copy to:

Sub-Regional Officer, M.P.C.Board, Bhiwandi:-He is directed to serve the directions to above industry and keep follow up and report the compliance thereof.