MAHARASHTRA POLLUTION CONTROL BOARD REGIONAL OFFICE-KALYAN

Tel. No. (0251) 2310167/2310212 Fax No. (0251) 2310192 Visit us on: http://mpcb.gov.in

E.mail: rokalyan@mpcb.gov.in



Siddhivinayak Sankul, 3rd Floor, Near Oak Baug, Station Road, Kalyan (West) – 421 301.

No.: MPCB/SROBhiwandi/ROK/CD/2005220005

Date:-22/05/2020

To, M/s. Mehrun Sizers, H.No.317, Kaneri,Tal.Bhiwandi

Dist. Thane-421302

Sub: Closure Directions u/s 33A of the Water (P&CP) Act, 1974 & u/s 31 A of the Air (P&CP) Act, 1981 r. w. Hazardous & Other Wastes (M&TM) Rules, 2016.

Ref:1) Consent granted by the Board to your industry.

- 2) Visit of Board officials to your unit on 04/03/2020.
 - 3) Proposal submitted by Sub-Regional Office, Bhiwandidtd.05/03/2020.
 - 4) Approval received from HQ dtd. 03/04/2020.
 - 5) Enforcement Policy Published by the Board vide dtd. 29/02/2016.

WHEREAS, you are operating the industry in the pollution prevention area declared under the Provisions of the Water (P&CP) Act, 1974 and the Air (P&CP) Act, 1981 and the Hazardous & Other Wastes (Management & Transboundary Movement) Rules, 2016.

AND WHEREAS, it is obligatory on your part to obtain Conditional Combined Consent and Authorization to operate your industrial plant to discharge sewage and trade effluent in water pollution prevention area subject to certain terms and conditions more precisely under the provisions of 26 of the Water (P&CP) Act, 1974 and section 21 of the Air (P&CP) Act, 1981 and Hazardous & Other Wastes (Management & Transboundary Movement) Rules, 2016.

AND WHEREAS, it was also obligatory on your part to provide adequate and efficient pollution control devices and take adequate measures to control air & water pollution from all sources so as to achieve the standards prescribed in the Environment (Protection) Act 1986 and to disposed the Hazardous Waste to CHWTSDF.

AND WHEREAS, this office has received proposal from Sub-Regional Office, MPCB, Bhiwandi and reported following non- compliances.

- You have not provided effluent treatment plant for treatment of effluent generated from sizing activity.
- 2. You have not provided air pollution control system i.e. wet scrubber to coal fired boiler and using unconsented fuel i.e. wood in boiler.
- 3. You have not provided air sampling arrangement like port hole, platform & ladder etc. as per consent condition.
- 4. You have not amended quantity of effluent and hazardous waste generation in existing consent.

Ş.

...2

AND WHEREAS, after examining all the reports and records available with this office I have come to the conclusion that you are knowingly and willfully violating the provisions of the Water (P&CP) Act, 1974 and Air (P&CP) Act, 1981.

NOW THEREFORE, in exercise of powers conferred upon me by the Board u/s 33A of the Water (P&CP) Act, 1974 and u/s 31A of the Air (P&CP) Act, 1981. I, the Regional Officer, Kalyan hereby direct you to stop your manufacturing activity taking all precautionary measures for safe closure of the unit within 48 hours from receipt of this direction. It may also be noted that, the competent authorities are being directed to disconnect the electricity and water supply to your unit.

This is issued with approval from competent authority.

Regional Officer, Kalyan

Copy submitted for information to:

- 1. Member Secretary, M.P.C. Board, Mumbai.
- 2. Law Officer M.P.C. Board, Mumbai.
- 3. Principal Scientific Officer, M.P.C. Board, Mumbai.

Copy f.w.cs to:

- 1) The Executive Engineer, Torrent Power Ltd., Old Agra Road, AnjurPhata, Bhiwandi-421302 - He is directed to disconnect electricity supply to the aforesaid unit after completion of 48 hours for safe closure of the unit & inform this office accordingly.
- 2) The Executive Engineer (Water Supply), Bhiwandi Nizampur Municipal Corporation, Bhiwandi He is directed to disconnect water supply to the aforesaid unit after completion of 48 hours for safe closure of the unit & inform this office accordingly

Copy to:

Sub-Regional Officer, M.P.C. Board, Bhiwandi: -He is directed to serve the directions to above industry and keep follow up and report the compliance thereof.